

FIG. 1A




FIG. 1B




FIG. 1C




FIG. 2A




FIG. 2B




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




Fig. 10




Fig. 11




Fig. 12

628

heating coil

626

624

5

632

distal septum

correcting wires

630

Fig. 13



[illegible]

Fig. 14






FIG. 16



2025-2026 "5259300"




Fig. 17